




4x



2x




2x




3x



2x



1x



2x



M8x20
6x



6,0x16
6x



M6x12
8x




6,4x12x1,5
8x




M6
8x


1




2






3



4






See mounting instructions for art
3-250-0 on next page.

3-250-0


1




2




3




4




5




6




7



8



9



WFI

WORKPLACES FOR INDUSTRIES



www.wfiab.se