






**18-40042**

**Power Cable Grounded**





## W300

1



**Drill hole in center beam.**



**Attach grounding cable with screw + nut.**



**Attach worktop to tableframe.  
Screw control unit into worktop.**



## W400

1



**Drill hole in table frame.**

**Attach grounding cable with screw + nut.**



**Attach worktop to tableframe.  
Screw control unit into worktop.**