




MultiWorkStation with crank





For MWS Small




For MWS Large




9-408-x Screw Kit




9-439-0 Wheel kit




1




2








3



4







8





M8x20
8x



M8
16x





M8-lock
8x



9





M6x16
2x



10




MWS large



M8x20
6x

M8
6x

MWS small



M8x20
4x

M8
4x

M8-lock
4x

