




4x




1x




1x



2x



2x




4x




2x

3x




2x

1x



1x



2x



M8x20  
6x



6,0x16  
6x




M6x12  
8x



6,4x12x1,5  
8x




M6  
8x




Dubbelhäftande Tejp  
4x





1




2









8





9




10






13




14








**15**



**16**







**WORKPLACES FOR INDUSTRIES**



[www.wfiab.se](http://www.wfiab.se)